

EXTERNAL WORK ORDER

REQUEST DETAILS

Reference Number	<input type="text" value="0000"/>	Submitted By	<input type="text" value="info@goodstays.co.nz"/>
Date Submitted	<input type="text" value="17/02/2021 01:27 PM"/>	Provider Contact	<input type="text" value="021 000 0000"/>
Service Provider	<input type="text" value="Dion Boland Painting"/>		

PROPERTY DETAILS

Property Code	<input type="text" value="XXXX0-00"/>	Address	<input type="text" value="Unit 1, 123 Smith Street"/>
Property Name	<input type="text" value="Queenstown Views"/>	Suburb	<input type="text" value="Queenstown"/>
		Postcode	<input type="text" value="9300"/>

JOB DETAILS

Priority	Low
Require Completion By	ASAP
Details of Works	At the bottom of the stairs going to the bedrooms on the lower level there are some movement cracks in the Gib please patch and repaint.



SIGN OFF

Completion Date	<input type="text" value="17/02/2021"/>	Signed - On behalf of Goodstays	<input type="text" value="Signed X"/>
Prepared By	<input type="text" value="Allan Baillie"/>		